

Дуф

У30



FI 2

$I_H = 10 A, C$

$I_{M.P.} = 10 A$

$I_H = 10 A$

$I_{\Delta} = 30 MA$



FI 2

$I_H = 10 A$

$I_{\Delta} = 30 MA$